

TEST-T4E R00 - loopback cable for testing FarSync T4E communications cards

Suitable for testing **FarSync T4E** communications cards in V.24, X.21, V.35 and RS530 configurations.

A label on the hood must read: **TEST-T4E R00**

All connections are local loops on a HIPPI 100-way Plug.

FROM		TO	
Signal	100 Pin Contact	Signal	100 Pin Contact
ATXa	2	BRXa	17
ATXb	52	BRXb	67
ARXa	4	BTXa	15
ARXb	54	BTXb	65
ARTSa	6	ACTSa	9
ARTSb	56	ACTSb	59
BRTSa	19	BCTSa	22
BRTSb	69	BCTSb	72
ADCDa	8	BDTRa	20
ADCDb	58	BDTRb	70
ADTRa	7	BDCDa	21
ADTRb	57	BDCDb	71
ATXCa	3	BTXCa	16
ATXCb	53	BTXCb	66
ARXCa	10	BRXCa	23
ARXCb	60	BRXCb	73

FarSite Communications Cable Connection Pinouts

FROM		TO	
Signal	100 Pin Contact	Signal	100 Pin Contact
CTXa	28	DRXa	43
CTXb	78	DRXb	93
CRXa	30	DTXa	41
CRXb	80	DTXb	91
CRTSa	32	CCTSa	35
CRTSb	82	CCTSb	85
DRTSa	45	DCTSa	48
DRTSb	95	DCTSb	98
CDCDa	34	DDTRa	46
CDCDb	84	DDTRb	96
CDTRa	33	DDCDa	47
CDTRb	83	DDCDB	97
CTXCa	29	DTXCa	42
CTXCb	79	DTXCb	92
CRXCa	36	DRXCa	49
CRXCb	86	DRXCb	99

Notes:

- The test connector should be used in conjunction with the **FarSync Card Test program**.